





Ref.: 087





- 01 X 1
- 02 X 1
- 03 X 1
- 04 X 1
- 05 X 1
- 06 X 2
- 07 X 6
- 08 X 1
- 09 X 1
- 10 X 2
- 11 X 4
- 12 X 2
- 13 X 2
- 14 X 2
- 15 X 4
- 16 X 2
- 17 X 2
- 18 X 2
- 19 X 1
- 20 X 1



2X




2X




A x 39




B x 1



C x 39




D x 15



E x 12



F x 6



G x 4



H x 1





J x 30




K x 2



L x 1





60 min




Trídte odpad




01

| | |
|---|---|
| Ax22 | Ex8 |
|  |  |
| 8.0x30 | 4.5x50 |






02

| |
|---|
| Dx6 |
|  |
| 4.0x35 |







03

| | |
|---|---|
| Dx6 | Cx7 |
|  |  |





04

| | | |
|---|---|---|
| Ax9 | Dx3 | Ex4 |
|  |  |  |






05

| | |
|------|--|
| Ax8 | 8.0x30 |
| Fx6 |  + 3/16x3/4 |
| Cx32 | 3.5x30 |






06

| | |
|------|---|
| Jx30 | 10x10 |
| Gx4 |  |
| Hx1 |  |



07

| Bx1 | Kx2 | Lx1 |
|---|---|---|
|  3.5x14 |  |  |

